

FIG. 1 (Prior Art)





FIG. 2

Capping Layer
20Å Co ₈₀ Fe ₂₀ or 40Å Ni ₈₀ Fe ₂₀ Free Layer
Pt Mn Spacer Layer
20Å Co ₈₀ Fe ₂₀ Biasing Layer
Pt Mn or IrMn Antiferromagnet
Underlayer
Si or Glass

FIG. 3






FIG. 5




FIG. 6